

Spectrum OS Firmware - Version 2.5 (LiteDimmer Spectrum AC600)**Date:** 06/30/2022

Issue	Consequence	Estimated Completion Date
The help QR code goes to a webpage that does not exist	When scanned, the help QR code does not go to a live website. A new QR code needs to be generated and updated in the software.	Early Q3 2022

NOTES:

- Visit www.litegear.com for latest firmware.