



Quick Start Guide

LiteDimmer Spectrum AC/DC200 and AC/DC400



Front Panel (Controls)

1. OLED Display
2. Function Buttons
3. Power LED Indicator
4. Data LED Indicator
5. Encoders (Top and Bottom)
6. Multi-Function Handle

Back Panel (Connections)

8. Power Switch
9. USB-A Port
10. EtherCon Ports
11. Wireless Antenna
12. 5-Pin DMX Connector
13. PDX Connector
14. 48V Battery Connector
15. PowerCon Connectors

Base

16. Multi-Function Handle
17. K-Mount Plate



Quick Start Guide

LiteDimmer Spectrum AC/DC200 and AC/DC400

Best practices for connecting to and disconnecting from the **PDX connector**.

1. Toggle the Power Switch to the OFF position.
2. Insert the cable connector into the PDX OUT port until the connector locks in place.
3. Toggle the Power Switch to the ON position.

Best practices for connecting to and disconnecting from the **Battery connector**.

1. Toggle the Power Switch to the OFF position.
2. Insert the cable connector into the BATTERY IN port until the connector locks.
3. Toggle the Power Switch to the ON position.

NOTE: The PDX and Battery connectors are not intended to be connected and disconnected when the dimmer is powered on.



BEFORE USE, SCAN OR GO TO:
LITEGEAR.COM/LDS200400