

Spare Parts



PWS-136X
Power Supply 6A, 100-250vac/12vdc,
4-Pin Xlr



1230007
PWRCORD-IEC / GER-
6.5FT



1230016
Pwr cord-IEC / US - 6ft



1270103
CT-Xlr-Plug-4F-Female




1270135
No longer available
CT-Panel-IEC-Male-
w/Fuse-Snapin



1300020
FU-5X20-Cer-Sloblow-
4A/250V



5080001
No longer available
Power Supply 136 Lid



6610031
No longer available
PWS 12VDC 6A Mod T0
13.2VDC



PRT-FET
Ballast Feet (24pk)



PRT-SC100
Screws F/Ballast Lid
(100pk)