

Spectrum OS Firmware - Version 3.0**Date:** 08/25/2023

Issue	Consequence	Estimated Completion Date
Gradient Mode on LiteMat 8 and Auroris does not perform as the user might expect.	Gradient mode is optimized for LiteMat 1, 2, 2L, 3, and 4. On a LiteMat 8 and Auroris, gradient mode with work in a zig-zag pattern. Future software will add new features to solve this issue.	Q1 2024

NOTES:

- Visit www.litegear.com for latest firmware.