




## Quick Start Guide

### LiteMat Spectrum 1, 2, 2L, 3, 4, 8 (2023)



BEFORE USE, SCAN OR GO TO:  
[LITEGEAR.COM/LMS18](https://www.litegear.com/LMS18)




#### Fixture Back

1. Pixel Control Cover
2. Mount Plate
3. PDX Connector
4. Inline Fuse Block

#### Fixture Front

5. Spectrum Light Engine
6. Protective Clear Film
7. Velcro Border
8. Mounting Eyelets





## Quick Start Guide

### LiteDimmer Spectrum AC/DC200 and AC/DC400

Best practice for connecting to and disconnecting from the **PDX connector**.

1. Toggle the Power Switch to the OFF position.
2. Insert the cable connector into the PDX OUT port until the connector locks in place.
3. Toggle the Power Switch to the ON position.

Best practice for connecting to and disconnecting from the **Battery connector**.

1. Toggle the Power Switch to the OFF position.
2. Insert the cable connector into the BATTERY IN port until the connector locks.
3. Toggle the Power Switch to the ON position.

**NOTE:** The PDX and Battery connectors are not intended to be connected and disconnected when the dimmer is powered on.



BEFORE USE, SCAN OR GO TO:  
[LITEGEAR.COM/LDS200400](https://LITEGEAR.COM/LDS200400)